




Maplewood Mall Stormwater Retrofit Project

Five Year Project Anniversary Inspection and Inventory

Project Overview




- 55 rainwater gardens (19 of which have enhanced sand filters)
- 6,733 sf permeable pavers
- 1 mile of tree trenches
- 354 trees
- A 5,700 gal cistern that catches roof runoff
- 20 million gallons of storm water per year intercepted from the parking lot (67% of total)

Overall Project Condition Notes



- The project is functioning well and weathering the storm of heavy mall traffic.
- Rain gardens and entry plantings are very healthy growing environments; water quality improvement as planned. Existing maintenance program very valuable.
- Tree trench design supporting good tree growth for some species, some species struggling. Overall design still very promising.
- Stormwater infrastructure in solid shape but some areas worth watching, potentially repairing.

Tree Trench Design



Infrastructure Condition

- Failing mortar and other construction concerns in 26 structures of the over 400 structures
- Sediments clogging trench drain inlet in some areas
- Recommend monitoring “Poor” structures, consider including in 2019/20 CIP repair work
- Assess sediment removal in Spring, coordinate with Mall staff and consider additional sweeping



Rain Gardens


- Two of the 55 rain gardens have long term standing water
- Likely due to sediment loading and compacted planting soil during construction
- Recommend removing clogged soils, refurbishing filtration systems
- Ongoing maintenance program has been critical to healthy plantings



Tree Health Grades

- A – Vigorous Growth (Full canopy)
- B – Strong Growth
- C – Fine Growth (75-50% canopy)
- D – Dying (<50% canopy)
- F1 – Dead (Replacement recommend)
- F2 – Dead (No replacement recommend)


Total Trees by Condition




Tree Health Statistics

- Tree trench creates a unique growing environment well suited to some species
- Species chosen for dry conditions have struggled
- Shallower trenches have higher tree mortality

Tree Trench - South Grove




Tree Trench - Northwest Grove




Species Health Summary

- Elm cultivars and swamp white oak showing outstanding growth
- Tree trenches creating a floodplain-like environment

Discovery Elm



Swamp White Oak



Species Health Summary


- Elm in West Grove
- Swamp white oak in East Grove
- Some trees installed at 2" DBH currently up to 5.5"+ DBH




Species Health Summary

- Honeylocust and Kentucky Coffeetree have struggled to thrive
- Other widely used urban trees failed to establish

Skyline Honeylocust



Espresso Kentucky Coffeetree



Healthy vs. Struggling Kentucky Coffeetree



Tree Trench Design Takeaways

- Tree trench creates a unique growing environment well suited to some species.
 - Species chosen for dry conditions have struggled.
 - Leave AgriDrain weirs out where already removed, be prepared to replace if we reach drought conditions. Once new trees established, slowly introduce the weirs throughout the project.
-

Tree Replacement and Maintenance Recommendations



- Continued sump cleanout and vegetation maintenance
- Replace entrance, select end island trees and all tree trench trees. (70 graded at D and F1)
- Use similar species to those that are currently thriving (elms, English oak/white oak hybrids, introduce river birch)
- Measure root growth and soil conditions during replacements
- Replace with younger tree stock to reduce transplant shock

Questions?